



SAFETYGRAM

17

CMTC SAFETY OFFICE LESSONS LEARNED

**EXCESSIVE SPEED AND
CAN DEFEAT ENVIRONMENT
IN BATTLE**



Background: This tank was attempting a right turn on a tank turn pad. Due to a combination of excessive speed and mud covered concrete the tank slid sideways for about 20 meters, struck a large rock and rolled over an embankment onto its top. The vehicle had to be turned on its side in order to evacuate one crew member.

Recommendation: Slow down and obey the speed limits!.

TRAIN TO WIN
Combat Maneuver Training
Center